


SETTING TABS- TO UNDER TO FRONT NOSE
SETTING TABS- TO UNDER TO FRONT NOSE
4'-0"
SCREWS HOLES TO NOSE
OPN FRAME
OPENINGS FOR FRAME
LOCATE WHEN MOUNTING
LOCATE HOLE WHEN MOUNTING
2'-0"
1'-7 1/4"
6-3/4"
1'-0 3/4"
1'-1"
2'-8 3/4"
BRACKET DETAIL
ANGLED UP 3"
BRACKET DETAIL