

**2629 RANDLEMAN ROAD
GREENSBORO, NC 27406
336-275-1494**

Center : 2

Vehicle : 20
License :
VIN :
Fleet #:
Engine : Trans :
Mileage :

OK	Bad	Recommendation	OK	Bad	Recommendation	OK	Bad	Recommendation
E9 COUPE								

I do not want my old parts X

Estimate Only

KORMAN AUTOWORKS, INC.

**2629 RANDLEMAN ROAD
GREENSBORO, NC 27406
336-275-1494**

Estimate #0013899**Date : 7/17/26****Page : 2****Center : 2**

Customer : KORMAN AUTOWORKS
Address : 2629 RANDLEMAN ROAD
City : GREENSBORO, NC 27406
Phone 1 : (336) Ext :
Phone 2 : (336) Ext :

Vehicle : 20**License :****VIN :****Fleet #:****Engine :****Trans :****Mileage :**

Op	Tech	Description		Labor	Parts	Subtotal
	Quan	Part Number	Part Description		Price	
0		E9 2000C/2000CS PARTS		0.00	1353.27	1353.27
1.00		54129634177	S/ROOF HANDLE GROMMET		0.00	
1.00		51141802320U	EMBLEM AUTOMATIC 2000C		0.00	
1.00		51145480184	GROMMET OLD STYLE METAL-		1.77	
1.00		51326654165U	FRT WINDOW BRCKT 2002/20		0.00	
1.00		51326654166U	FRT WINDOW BRCKT 2002/20		0.00	
1.00		62111354848AU	GAUGE SUPPORT 2000C/CS-U		0.00	
1.00		62111812236U	GAUGE SPACER 200C/CS-USE		0.00	
3.00		62111812237U	GAUGE RING 200C/CS-USED		0.00	
1.00		62131357110U	CLOCK 2000C/CS-USED/SQUA		0.00	
		2000C/CS MADE UP PART # FOR BOTH BK BOOSTER MOUNTS FROM 2000C/CS		0.00		
1.00		34331103000U	BK BOOSTER MT KIT 2000C-		0.00	
		E9 ENGINE ELECTRICAL:		0.00	3489.99	3489.99
		NOTES ON 1231 1 272 226 ALTERNATOR, E9-Alternator 55 A with integrated voltage controller for all models from 1973 up with steering pump drive from the crankshaft				
2.00		BC12	BOSCH IGN COIL BLUE/SPOR		80.22	
1.00		RC18	BOSCH RED COIL, SEE 0227		23.12	
1.00		1201038	IGN POINTS M30 74-77		9.81	
2.00		1202095	CONDENSOR M30 75-77 M30		14.44	
3.00		1203008	DIST CAP M30 75-81		98.94	
1.00		1203014	DIST CAP M30 69-74		29.96	

OK	Bad	Recommendation	OK	Bad	Recommendation	OK	Bad	Recommendation
E9 COUPE								

You have the right to receive a written estimate or to waive receipt of that estimate if the cost of repairs will exceed \$350.00. We will provide an estimate for your specific problem/repair. Our hourly rate is \$150.00.

I authorize Korman Autoworks, Inc. to diagnose and repair my vehicle without providing a written estimate.

(This repair)X_____ (Permanently)X_____

I authorize repairs that do not exceed \$_____. X_____

I request a written estimate X_____

I wish to receive my old parts X_____ Received (initial) X_____

I do not want my old parts X_____

Labor : \$0.00**Parts : \$47,596.47****Sublet : \$0.00****Other Fees : \$0.00****Supplies/Haz \$0.00****Subtotal : \$47,596.47****Sales Tax : \$3,209.25****Total : \$50,805.72****Estimate Only**

**2629 RANDLEMAN ROAD
GREENSBORO, NC 27406
336-275-1494**

Center : 2

Vehicle : 20
License :
VIN :
Fleet #:
Engine : Trans :
Mileage :

OK	Bad	Recommendation	OK	Bad	Recommendation	OK	Bad	Recommendation
E9 COUPE								

I do not want my old parts X

Estimate Only

KORMAN AUTOWORKS, INC.

**2629 RANDLEMAN ROAD
GREENSBORO, NC 27406
336-275-1494**

Estimate #0013899**Date : 7/17/26****Page : 4****Center : 2**

Customer : KORMAN AUTOWORKS
Address : 2629 RANDLEMAN ROAD
City : GREENSBORO, NC 27406
Phone 1 : (336) Ext :
Phone 2 : (336) Ext :

Vehicle : 20**License :****VIN :****Fleet #:****Engine :****Mileage :****Trans :**

Op	Tech	Description			Labor	Parts	Subtotal
	Quan	Part Number	Part Description	Reason for Replacement		Price	
16.00		7800	SOLEX JETS			48.00	
2.00		99006.66K	INTAKE M30 W/3 DCOES			254.02	
1.00		13111255742	CARB RPR KIT M30 W/OEM C			35.00	
1.00		13211250903	SHIFT BALL JOINT E3/E9			3.00	
2.00		13310075752	FUEL PUMP BUSHING M10/M3			3.90	
1.00		13311260677	FUEL PUMP M30-CARB-SEE N			88.51	
25.00		13311680109	F/P INSULATOR W/GSKT M10			25.00	
1.00		16111744369	GAS TANK ORING 2002/E3/9			3.89	
1.00		16121105332	GAS TANK ORING 2002/E3/E			9.93	
1.00		16121130106	FUEL FILTER MT / EARLY M			2.50	
2.00		3541K000	GAS PEDAL BALL-COUPE			43.56	
1.00		13721271254	AIR FILTER V/APPS			12.25	
4.00		13111263266	SOLEX THROTTLE PLATE GSK			52.00	
1.00		13541256447	T/BODY GSKT M30 E3/9/12/			6.50	
1.00		13721256550U	AIR BOX E3/E9 W/ F.I.-US			0.00	
2.00		13729055213	AIR FILTER 3.0CSI/530 9/			20.22	
		E9 COOLING			0.00	3692.74	3692.74
6.00		17111E9	AL RADIATOR 3.0CS (10/73			3469.74	
4.00		17111100000	RADIATOR MT UPR-E9			48.00	
5.00		17111102866U	RADIATOR E9 12/68-10/73			125.00	
1.00		17111103176U	EXPANSION TANK E9-USED			25.00	
1.00		17111115083U	FAN SHROUD E9-USED			25.00	
1.00		516442000CU	RADIATOR SUPPORT 2000C/C			0.00	
		E9 EXHAUST			0.00	1662.11	1662.11

OK	Bad	Recommendation	OK	Bad	Recommendation	OK	Bad	Recommendation
E9 COUPE								

You have the right to receive a written estimate or to waive receipt of that estimate if the cost of repairs will exceed \$350.00. We will provide an estimate for your specific problem/repair. Our hourly rate is \$150.00.

I authorize Korman Autoworks, Inc. to diagnose and repair my vehicle without providing a written estimate.

(This repair)X_____ (Permanently)X_____

I authorize repairs that do not exceed \$_____. X_____

I request a written estimate X_____

I wish to receive my old parts X_____ Received (initial) X_____

I do not want my old parts X_____

Labor : \$0.00**Parts : \$47,596.47****Sublet : \$0.00****Other Fees : \$0.00****Supplies/Haz \$0.00****Subtotal : \$47,596.47****Sales Tax : \$3,209.25****Total : \$50,805.72****Estimate Only**

KORMAN AUTOWORKS, INC.

**2629 RANDLEMAN ROAD
GREENSBORO, NC 27406
336-275-1494**

Estimate #0013899**Date : 7/17/26****Page : 5****Center : 2**

Customer : KORMAN AUTOWORKS
Address : 2629 RANDLEMAN ROAD
City : GREENSBORO, NC 27406
Phone 1 : (336) Ext :
Phone 2 : (336) Ext :

Vehicle : 20**License :****VIN :****Fleet #:****Engine :****Trans :****Mileage :**

Op	Tech	Description			Labor	Parts	Subtotal
Quan	Part Number	Part Description	Reason for Replacement			Price	
1.00	18111245339	TAILPIPE E9-NLA 55MM OD				200.00	
1.00	18121245240	EXH BOW-E9 NLA				6.00	
2.00	18121245566	EXH BRACKET E3/E9				16.00	
2.00	18211102741	EXH BRCKT E3/9/12				12.00	
1.00	18211102888	EXH CLAMP E9				14.80	
2.00	18211103757	EXH HANGER E9				58.20	
1.00	18211245177	EXH SUPPORT E3/9				15.00	
1.00	18211246379	EXH BOW E3/9/12/24				7.54	
4.00	18214690157	EXH HANGER E9				117.60	
1.00	18215138	STAHL HDR BIG SIX E3/9/1				968.76	
1.00	182110016	CERAMIC 6CYL HDR COATING				230.13	
3.00	18119067822	EXH ORING M30-EARLY				16.08	
	E9 CLUTCH				0.00	2653.41	2653.41
1.00	2121147006	SACHS HD P/P 240MM				327.62	
3.00	2152112030S	S/S CLUTCH LINE 5 SPD 02				91.47	
2.00	2152115630S	S/S CLUTCH LINE 2002/E3/				57.34	
1.00	11221706577U	FLYWHEEL M30 (NON-MO)-US				50.00	
1.00	21111200212U	BELLHOUSING M30 4 SPD E3				45.00	
1.00	21111228048U	BELLHOUSING M30-MOTRONIC				101.00	
1.00	21521102060	SLAVE CYL E3/E9/M1				186.98	
1.00	21521102721	SLAVE CYL PIVOT BOLT E3/				3.00	
1.00	21521104262	CLUTCH M/C E3/9/2002Ti				428.45	
3.00	25250004	SHORT SHIFT KIT E3,9,12,				525.24	
1.00	21521119541	MASTER CYL CAP 2002/E23/				4.68	

OK	Bad	Recommendation	OK	Bad	Recommendation	OK	Bad	Recommendation
E9 COUPE								

You have the right to receive a written estimate or to waive receipt of that estimate if the cost of repairs will exceed \$350.00. We will provide an estimate for your specific problem/repair. Our hourly rate is \$150.00.

I authorize Korman Autoworks, Inc. to diagnose and repair my vehicle without providing a written estimate.

(This repair)X_____ (Permanently)X_____

I authorize repairs that do not exceed \$_____. X_____

I request a written estimate X_____

I wish to receive my old parts X_____ Received (initial) X_____

I do not want my old parts X_____

Labor : \$0.00**Parts : \$47,596.47****Sublet : \$0.00****Other Fees : \$0.00****Supplies/Haz \$0.00****Subtotal : \$47,596.47****Sales Tax : \$3,209.25****Total : \$50,805.72****Estimate Only**

KORMAN AUTOWORKS, INC.

**2629 RANDLEMAN ROAD
GREENSBORO, NC 27406
336-275-1494**

Estimate #0013899**Date : 7/17/26****Page : 6****Center : 2**

Customer : KORMAN AUTOWORKS
Address : 2629 RANDLEMAN ROAD
City : GREENSBORO, NC 27406
Phone 1 : (336) Ext :
Phone 2 : (336) Ext :

Vehicle : 20**License :****VIN :****Fleet #:****Engine :****Mileage :****Trans :**

Op	Tech	Description		Labor	Parts	Subtotal
	Quan	Part Number	Part Description	Reason for Replacement	Price	
0		E9 CLUTCH		0.00	2653.41	2653.41
1.00		21521102935	CLUTCH M/C R/B KIT (19.0		42.20	
1.00		25111205384U	SHIFT SUPPORT E3/9/12/24		0.00	
3.00		25250004	SHORT SHIFT KIT E3,9,12,		552.24	
1.00		21111225493U	BELLHOUSING M30 5 SPD NO		193.75	
1.00		21521114540	BRACKET M30 5 SPD CONV		13.74	
1.00		35411105414	GAS PEDAL E3/9/12/21/24/		30.70	
		E9 TRANSMISSION		0.00	2150.21	2150.21
2.00		23009065645	TRANS GSKT SET M10/4 SPE		106.24	
2.00		23711175732	TRANS MT M30 EARLY		102.22	
2.00		24341203479	A/T KICKDOWN CABLE E3/E9		26.00	
2.00		23001209490U	TRANSMISSION 4 SPD BIG 6		150.00	
2.00		23211202751	SPEEDO DRIVE ADAPTER M30		122.20	
2.00		23211202751U	SPEEDO DRIVE ADAPTER M30		63.00	
1.00		23001208727RB	TRANSMISSION 5 SPD O/D M		1547.61	
1.00		25111220217	SHIFT LEVER BIG 6 LWR/OL		32.94	
		E9 DRIVESHAFT		0.00	33.46	33.46
2.00		26111206502	CTR SUPPORT BRG-2002/E9		33.46	
		E9 STEERING		0.00	1108.58	1108.58
1.00		12311274747	P/S PUMP BRCKT M30/S38		37.76	
2.00		32211100849	IDLER ARM BUSHING E3/E9		145.32	
6.00		32211101374	TIE ROD SEAL 2002/BIG 6		17.10	
3.00		32211108363	TIE ROD BOOT 02/E3/9/12/		34.50	

OK	Bad	Recommendation	OK	Bad	Recommendation	OK	Bad	Recommendation
E9 COUPE								

You have the right to receive a written estimate or to waive receipt of that estimate if the cost of repairs will exceed \$350.00. We will provide an estimate for your specific problem/repair. Our hourly rate is \$150.00.

I authorize Korman Autoworks, Inc. to diagnose and repair my vehicle without providing a written estimate.

(This repair)X_____ (Permanently)X_____

I authorize repairs that do not exceed \$_____. X_____

I request a written estimate X_____

I wish to receive my old parts X_____ Received (initial) X_____

I do not want my old parts X_____

Labor : \$0.00**Parts : \$47,596.47****Sublet : \$0.00****Other Fees : \$0.00****Supplies/Haz \$0.00****Subtotal : \$47,596.47****Sales Tax : \$3,209.25****Total : \$50,805.72****Estimate Only**

KORMAN AUTOWORKS, INC.

**2629 RANDLEMAN ROAD
GREENSBORO, NC 27406
336-275-1494**

Estimate #0013899**Date : 7/17/26****Page : 7****Center : 2**

Customer : KORMAN AUTOWORKS
Address : 2629 RANDLEMAN ROAD
City : GREENSBORO, NC 27406
Phone 1 : (336) Ext :
Phone 2 : (336) Ext :

Vehicle : 20**License :****VIN :****Fleet #:****Engine :****Trans :****Mileage :**

Op	Tech	Description		Labor	Parts	Subtotal
	Quan	Part Number	Part Description	Reason for Replacement	Price	
0		E9 STEERING				
	2.00	32211114843	TIE ROD END E3/9/12/23/2		70.00	1108.58
	1.00	32311101111U	STEERING COLUMN TRIM E3/		25.00	
	1.00	32311104156	STEERING COLUMN BOOT E3/		25.00	
	1.00	32311117300U	TRIM PANEL UPR E3/9/23-U		25.00	
	1.00	32321110017	IGN LOCK W/KEY E3/E9		200.00	
	1.00	32331111401U	S/WHEEL E9-USED		25.00	
	2.00	32411101150U	P/S TANK E3/9/12/24-USED		70.00	
	1.00	32411101151U	P/S TANK HOLDER E9-USED		15.00	
	2.00	32411104357	P/S FILTER E3/E9/E12/E24		19.00	
	1.00	32411117565	P/S HOSE E3/E9 PRESSURE-		100.00	
	1.00	32411117621	P/S PUMP SHAFT SEAL E9/1		10.00	
	1.00	332202204	POLY T/ARM BUSHINGS (4)		25.00	
	12.00	31351114570	ENDLINK CUP V/APPS		75.96	
	32.00	31351125712	S/BAR ENDLINK BUSHING 20		51.20	
	8.00	31352654108	S/BAR SPACER SLEEVE		77.92	
	2.00	31421100626	STRUT ROD WASHER TII/BIG		4.00	
	18.00	32131104785	ORING P/S E3/9/12/12		27.00	
	0.00	32331112222U	HORN RING 2002/2000C-USE		0.00	
	1.00	32332782050U	S/WHEEL 2000C/CS >2/70-U		0.00	
	1.00	32411121836	P/S TANK CVR V/APPS		28.82	
		E9 DIFFERENTIAL				
	1.00	33101203122U	DIFF S/LOADER 4.10 L/S-U		1250.00	5655.00
	1.00	33101203127RB	DIFF/LOADER 3.64 25% RE		3075.00	

OK	Bad	Recommendation	OK	Bad	Recommendation	OK	Bad	Recommendation
E9 COUPE								

You have the right to receive a written estimate or to waive receipt of that estimate if the cost of repairs will exceed \$350.00. We will provide an estimate for your specific problem/repair. Our hourly rate is \$150.00.

I authorize Korman Autoworks, Inc. to diagnose and repair my vehicle without providing a written estimate.

(This repair)X_____ (Permanently)X_____

I authorize repairs that do not exceed \$_____. X_____

I request a written estimate X_____

I wish to receive my old parts X_____ Received (initial) X_____

I do not want my old parts X_____

Labor : \$0.00**Parts : \$47,596.47****Sublet : \$0.00****Other Fees : \$0.00****Supplies/Haz \$0.00****Subtotal : \$47,596.47****Sales Tax : \$3,209.25****Total : \$50,805.72****Estimate Only**

KORMAN AUTOWORKS, INC.

**2629 RANDLEMAN ROAD
GREENSBORO, NC 27406
336-275-1494**

Estimate #0013899**Date : 7/17/26****Page : 8****Center : 2**

Customer : KORMAN AUTOWORKS
Address : 2629 RANDLEMAN ROAD
City : GREENSBORO, NC 27406
Phone 1 : (336) Ext :
Phone 2 : (336) Ext :

Vehicle : 20**License :****VIN :****Fleet #:****Engine :****Mileage :****Trans :**

Op	Tech	Description		Labor	Parts	Subtotal
	Quan	Part Number	Part Description	Reason for Replacement	Price	
0		E9 DIFFERENTIAL		0.00	5655.00	5655.00
	1.00	33126390	3.90 GEAR SET E3/E9		0.00	
	1.00	33126410	4.10 GEAR SET E3/E9		0.00	
	1.00	33126292	2.92 GEAR SET E3/E9		0.00	
	10.00	331201002	DELRIN T/ARM BUSHING KIT		1330.00	
		E9 SIDE LOADER DIFFERENTIAL REBUILD PARTS		0.00	409.46	409.46
	2.00	33121203615	PINION BRG V/APPS		65.08	
	2.00	33121203616	PINION BRG V/APPS		75.50	
	2.00	33113704163	ORING SIDE LOADER DIFF-N		18.18	
	2.00	33121202462	DIFF O/P SHAFT SEAL V/AP		25.08	
	6.00	07119981720	DIFF BRG-SIDE LOADER-NOT		204.24	
	116.00	07119963355	GASKET RING M22X27 AL		6.96	
	2.00	33121744368	CRUSH SLEEVE V/APPS		14.42	
		E9 SUSPENSION		0.00	3725.38	3725.38
	2.00	31106004030	S/BAR KIT BIG 6 28/22A		664.60	
	1.00	31121104387	CTR ARM E3/E9 D/S		152.34	
	1.00	31121104388	CTR ARM E3/E9 P/S		149.32	
	8.00	31122614100	CTR ARM BUSHING 2002/E3/		137.12	
	5.00	31122614103	CTR ARM BUSHING 2002/E3/		105.00	
	1.00	31122614161	CTR ARM WASHER 2002/E3/9		3.17	
	8.00	31212031750	WHEEL STUD 2002/E3/E9-FR		52.32	
	2.00	31212634103	WHEEL BRG 2002TII/BIG 6-		10.84	
	4.00	31212634106	WHEEL BRG 2002TII/BIG 6-		34.76	

OK	Bad	Recommendation	OK	Bad	Recommendation	OK	Bad	Recommendation
E9 COUPE								

You have the right to receive a written estimate or to waive receipt of that estimate if the cost of repairs will exceed \$350.00. We will provide an estimate for your specific problem/repair. Our hourly rate is \$150.00.

I authorize Korman Autoworks, Inc. to diagnose and repair my vehicle without providing a written estimate.

(This repair)X_____ (Permanently)X_____

I authorize repairs that do not exceed \$_____. X_____

I request a written estimate X_____

I wish to receive my old parts X_____ Received (initial) X_____

I do not want my old parts X_____

Labor : \$0.00**Parts : \$47,596.47****Sublet : \$0.00****Other Fees : \$0.00****Supplies/Haz \$0.00****Subtotal : \$47,596.47****Sales Tax : \$3,209.25****Total : \$50,805.72****Estimate Only**

KORMAN AUTOWORKS, INC.

**2629 RANDLEMAN ROAD
GREENSBORO, NC 27406
336-275-1494**

Estimate #0013899**Date : 7/17/26****Page : 9****Center : 2**

Customer : KORMAN AUTOWORKS
Address : 2629 RANDLEMAN ROAD
City : GREENSBORO, NC 27406
Phone 1 : (336) Ext :
Phone 2 : (336) Ext :

Vehicle : 20**License :****VIN :****Fleet #:****Engine :****Trans :****Mileage :**

Op	Tech	Description		Labor	Parts	Subtotal
	Quan	Part Number	Part Description	Reason for Replacement	Price	
4.00		31331101663	UPR SUP BRG E3/9/12/24>9		1220.40	
1.00		33321106869U	T/ARM L/R E9-USED		100.00	
1.00		33321106870U	T/ARM R/R E9-USED		100.00	
1.00		33411100603	AXLE SHIM E3/9/12/23/24		3.00	
7.00		33411107512	WHEEL BRG KIT BIG 6		190.61	
3.00		33521117677	SHOCK MT WASHER BIG 6/E2		27.00	
2.00		33531104057	HOSE E3/E9		6.74	
1.00		31336028	S/BAR BIG 6 28MM FRT		100.00	
2.00		B46-0813	BILSTEIN SHOCK E9 68-74		203.64	
2.00		P36-0024	BILSTEIN E3/9/12-FRT		343.14	
3.00		31121123552	THRUST ROD BUSHING (PR)		121.38	
		E9 BRAKE			0.00	2353.40
						2353.40
1.00		34111101093A	BK CALIPHER 2002TII/BIG		70.56	
1.00		34111101094A	BK CALIPHER 2002TII/BIG		70.00	
1.00		34111101094U	BK CALIPHER 2002TII/ BIG		20.00	
1.00		34111101859U	BK CALIPER TII/E3/9 L/F-		50.00	
1.00		34111101860U	BK CALIPER TII/E3/9 R/F-		50.00	
1.00		34111103232	BK BLEEDER W/CAP E3/9/12		6.00	
1.00		34111103330	BK PAD CLIP BIG 6 NLA		4.00	
3.00		34111113664	BK HDWE KIT 2002/E3/9/12		44.61	
8.00		34111153198	BK BLEEDER DUST CAP		59.68	
3.00		34111159257	BK PAD SET 2002TII/3.0-A		130.02	
1.00		34211113665	BK HDWE KIT E9/E12 (REAR		26.00	
1.00		34211119211U	BK CALIPER E3/E9 (VENTED		50.00	

OK	Bad	Recommendation	OK	Bad	Recommendation	OK	Bad	Recommendation
E9 COUPE								

You have the right to receive a written estimate or to waive receipt of that estimate if the cost of repairs will exceed \$350.00. We will provide an estimate for your specific problem/repair. Our hourly rate is \$150.00.

I authorize Korman Autoworks, Inc. to diagnose and repair my vehicle without providing a written estimate.

(This repair)X _____ (Permanently)X _____

I authorize repairs that do not exceed \$ _____. X _____

I request a written estimate X _____

I wish to receive my old parts X _____ Received (initial) X _____

I do not want my old parts X _____

Labor : \$0.00**Parts : \$47,596.47****Sublet : \$0.00****Other Fees : \$0.00****Supplies/Haz \$0.00****Subtotal : \$47,596.47****Sales Tax : \$3,209.25****Total : \$50,805.72****Estimate Only**

KORMAN AUTOWORKS, INC.

**2629 RANDLEMAN ROAD
GREENSBORO, NC 27406
336-275-1494**

Estimate #0013899**Date : 7/17/26****Page : 10****Center : 2**

Customer : KORMAN AUTOWORKS
Address : 2629 RANDLEMAN ROAD
City : GREENSBORO, NC 27406
Phone 1 : (336) **Ext :**
Phone 2 : (336) **Ext :**

Vehicle : 20**License :****VIN :****Fleet #:****Engine :****Mileage :****Trans :**

Op	Tech	Description	Labor	Parts	Subtotal
Quan	Part Number	Part Description	Reason for Replacement	Price	
0	E9 BRAKE		0.00	2353.40	2353.40
1.00	34211119212U	BK CALIPER E3/E9 (VENTED		50.00	
1.00	34311120832	BK MASTER CYL E3/9/12/24		202.96	
2.00	34311120832U	BK MASTER CYL E3/9/12/24		133.00	
2.00	34314650172	BK M/C WASHER E3/9/10/12		4.00	
4.00	34321102417	BK LINE GROMMET 02/E3/9/		26.88	
1.00	34321112400	BK MASTER CYL RESERVOIR-		25.99	
2.00	34331103346U	BK BOOSTER CORE E3/9/12		300.00	
1.00	34334650142U	BK BOOSTER CAP BIG 6/ 20		15.00	
1.00	34411100782	BK SHOE LEVER E9/E21		3.50	
3.00	34411101501U	EBRAKE BOOT 02/E3/9/21/2		15.00	
1.00	34411112702U	EBRAKE LEVER E9-USED		15.00	
4.00	34411151641	BK SHOE SPRING E3/9/23/2		18.00	
1.00	REPD111M	BK PAD SET E3/9/12/24 >8		33.00	
8.00	34211116476	BK SHOE PIN CLIP 2000C/C		12.08	
4.00	34211117860	BK SHOE WAVE WASHER		2.04	
1.00	34213061725	BK BOW V/APPS-NLA PART		13.87	
11.00	34213660163	BK SHOE SHIM 2002/E9/21		10.45	
4.00	34213660164	BK SHOE RIVET 2002/E9/E2		7.04	
2.00	34213660185	BK SHOE SPRING 2002/E9/2		13.56	
2.00	34213660186	BK SHOE SPRING-LWR 2002/		13.02	
1.00	34213660190	BK DRUM THRUST ROD-L 200		32.84	
1.00	34213660191	BK DRUM THRUST ROD-R 200		37.49	
2.00	34311103743	BK MASTER CYL R/B KIT (2		199.70	

OK	Bad	Recommendation	OK	Bad	Recommendation	OK	Bad	Recommendation
E9 COUPE								

You have the right to receive a written estimate or to waive receipt of that estimate if the cost of repairs will exceed \$350.00. We will provide an estimate for your specific problem/repair. Our hourly rate is \$150.00.

I authorize Korman Autoworks, Inc. to diagnose and repair my vehicle without providing a written estimate.

(This repair)X_____ (Permanently)X_____

I authorize repairs that do not exceed \$_____. X_____

I request a written estimate X_____

I wish to receive my old parts X_____ Received (initial) X_____

I do not want my old parts X_____

Labor : \$0.00**Parts :** \$47,596.47**Sublet :** \$0.00**Other Fees :** \$0.00**Supplies/Haz** \$0.00**Subtotal :** \$47,596.47**Sales Tax :** \$3,209.25**Total :** \$50,805.72**Estimate Only**

KORMAN AUTOWORKS, INC.

**2629 RANDLEMAN ROAD
GREENSBORO, NC 27406
336-275-1494**

Estimate #0013899**Date : 7/17/26****Page : 11****Center : 2**

Customer : KORMAN AUTOWORKS
Address : 2629 RANDLEMAN ROAD
City : GREENSBORO, NC 27406
Phone 1 : (336) Ext :
Phone 2 : (336) Ext :

Vehicle : 20**License :****VIN :****Fleet #:****Engine :****Mileage :****Trans :**

Op	Tech	Description		Labor	Parts	Subtotal
	Quan	Part Number	Part Description	Reason for Replacement	Price	
0		E9 BRAKE			2353.40	2353.40
1.00		34311120478	BK MASTER CYL 2000C/2800		289.15	
4.00		34321159879	BK LINE RUBBER 12.5" F/F		38.76	
1.00		34326755549	BK LINE M10X190		20.50	
1.00		34326755555	BK LINE M10X260		27.08	
1.00		34326755569	BK LINE M10X400		21.73	
1.00		34331103261	BK BOOSTER ELBOW		4.13	
2.00		34331103316	BK BOOSTER NIPPLE 2002/B		98.70	
4.00		34321159879	BK LINE RUBBER 12.5" F/F		38.76	
1.00		34326755549	BK LINE M10X190		20.50	
1.00		34411152228	EBRAKE CABLE HANGER V/AP		2.00	
2.00		61348648111	CIGAR LIGHTER FILLAMENT		26.80	
		E9 S/S BRAKE LINE KIT			66.93	66.93
4.00		125FF	S/S BK LINE 12.5" F/F		47.56	
1.00		875FF	S/S BK LINE 8.75" F/F		9.65	
1.00		875MF	S/S BK LINE 8.75" M/F		9.72	
		E9 PEDAL			80.32	80.32
4.00		35411100674	PEDAL BUSHING TII/E3/E9		10.16	
4.00		35214540122	PEDAL PAD BK AUTOMATIC 0		58.40	
3.00		35314640116	PEDAL BUSHING-V/A		6.15	
1.00		35411104248	PEDAL CLAMP-NLA		5.61	
		E9 WHEEL			117.87	117.87
4.00		36131114435	WHEEL CENTER CAP E3/9/12		40.00	

OK	Bad	Recommendation	OK	Bad	Recommendation	OK	Bad	Recommendation
E9 COUPE								

You have the right to receive a written estimate or to waive receipt of that estimate if the cost of repairs will exceed \$350.00. We will provide an estimate for your specific problem/repair. Our hourly rate is \$150.00.

I authorize Korman Autoworks, Inc. to diagnose and repair my vehicle without providing a written estimate.

(This repair)X_____ (Permanently)X_____

I authorize repairs that do not exceed \$_____. X_____

I request a written estimate X_____

I wish to receive my old parts X_____ Received (initial) X_____

I do not want my old parts X_____

Labor : \$0.00**Parts : \$47,596.47****Sublet : \$0.00****Other Fees : \$0.00****Supplies/Haz \$0.00****Subtotal : \$47,596.47****Sales Tax : \$3,209.25****Total : \$50,805.72****Estimate Only**

KORMAN AUTOWORKS, INC.

**2629 RANDLEMAN ROAD
GREENSBORO, NC 27406
336-275-1494**

Estimate #0013899**Date : 7/17/26****Page : 12****Center : 2**

Customer : KORMAN AUTOWORKS
Address : 2629 RANDLEMAN ROAD
City : GREENSBORO, NC 27406
Phone 1 : (336) Ext :
Phone 2 : (336) Ext :

Vehicle : 20**License :****VIN :****Fleet #:****Engine :****Mileage :****Trans :**

Op	Tech	Description		Labor	Parts	Subtotal
	Quan	Part Number	Part Description		Price	
0		E9 WHEEL		0.00	117.87	117.87
	1.00	36121119332	VALVE STEM BOLT IN/OEM A		8.21	
	16.00	36131113132	LUGNUT ACORN-OEM W/ALLOY		57.92	
	2.00	51141801526	TIRE DECAL 2002/E3/9/12		11.74	
		E9 BODY		0.00	82.60	82.60
	1.00	41111809681	STRUT SUPORT E3/E9 L/F		75.00	
	10.00	46637664250	SCREW M3.5X15-SHEEL META		7.60	
		E9-TRIM		0.00	12627.30	12627.30
	148.00	51326SPECIAL	WINDOW RUBBER PER FT/ 1/		307.84	
	3.00	51461E9E10	TRUNK TRIM PANEL CLIP KI		89.22	
	2.00	41615780135U	HOOD BOW E9/2000C-USED		50.00	
	1.00	51111810519U	FRT BUMPER O/RIDEER E9 D		35.00	
	6.00	51121811179	BUMPER SEAL E9-REAR		36.00	
	134.00	51131804205	MOLDING CLIP 2002/E9		214.40	
	55.00	51131805091	MOLDING CLIP E9		134.75	
	2.00	51131807716	MOLDING CLIP E3/9/12-ROC		14.00	
	16.00	51131808841	MOLDING CLIP E9/12/23/24		8.48	
	3.00	51131810538U	MOLDING E9 CTR NOSE-USED		225.00	
	2.00	51131810541U	MOLDING E9 HOOD L/F-USED		0.00	
	2.00	51131810542U	MOLDING E9 HOOD R/F-USED		0.00	
	1.00	51131810543	MOLDING E9 D/S DOOR		185.84	
	4.00	51131810543U	MOLDING E9 D/S DOOR-USED		0.00	
	1.00	51131810544	MOLDING E9 P/S DOOR		185.84	

OK	Bad	Recommendation	OK	Bad	Recommendation	OK	Bad	Recommendation
E9 COUPE								

You have the right to receive a written estimate or to waive receipt of that estimate if the cost of repairs will exceed \$350.00. We will provide an estimate for your specific problem/repair. Our hourly rate is \$150.00.

I authorize Korman Autoworks, Inc. to diagnose and repair my vehicle without providing a written estimate.

(This repair)X_____ (Permanently)X_____

I authorize repairs that do not exceed \$_____. X_____

I request a written estimate X_____

I wish to receive my old parts X_____ Received (initial) X_____

I do not want my old parts X_____

Labor : \$0.00**Parts : \$47,596.47****Sublet : \$0.00****Other Fees : \$0.00****Supplies/Haz \$0.00****Subtotal : \$47,596.47****Sales Tax : \$3,209.25****Total : \$50,805.72****Estimate Only**

KORMAN AUTOWORKS, INC.

**2629 RANDLEMAN ROAD
GREENSBORO, NC 27406
336-275-1494**

Estimate #0013899**Date : 7/17/26****Page : 13****Center : 2**

Customer : KORMAN AUTOWORKS
Address : 2629 RANDLEMAN ROAD
City : GREENSBORO, NC 27406
Phone 1 : (336) Ext :
Phone 2 : (336) Ext :

Vehicle : 20**License :****VIN :****Fleet #:****Engine :****Trans :****Mileage :**

Op	Tech	Description		Labor	Parts	Subtotal
Quan	Part Number	Part Description	Reason for Replacement		Price	
4.00	51131810544U	MOLDING E9 P/S DOOR-USED			0.00	
1.00	51131810545	MOLDING E9 BELT TRIM-L/R			456.68	
4.00	51131810545U	MOLDING E9 BELT TRIM L/R			0.00	
4.00	51131810546U	MOLDING E9 BELT TRIM R/R			0.00	
1.00	51131810559U	MOLDING E9 LWR/LEFT-NLA-			0.00	
1.00	51131810777U	B PILLAR CVR E9 D/S-USED			0.00	
1.00	51131810778U	B PILLAR CVR E9 P/S-USED			0.00	
1.00	51131811149	FENDER GRILL DECAL E9 D/			0.00	
1.00	51131811150	FENDER GRILL DECAL E9 P/			0.00	
2.00	51131811483U	GRILL E9 D/S-USED			0.00	
1.00	51131811484U	GRILL E9 P/S NLA-USED			0.00	
1.00	51131812919	REAR COVER E9-NLA			241.79	
1.00	51131812919U	REAR COVER E9-NLA-USED			0.00	
1.00	51131813025	DRIP RAIL E9 D/S			414.95	
2.00	51131813025U	DRIP RAIL E9 D/S-USED			0.00	
1.00	51131813026	DRIP RAIL E9 P/S			423.40	
1.00	51131813026U	DRIP RAIL E9 P/S-USED			0.00	
1.00	51131826809	GRILL CENTER E3/E9 EURO			593.54	
1.00	51131827275U	HOOD GRILL E9 L/BLK-USED			0.00	
1.00	51131827276U	HOOD GRILL E9 R/BLK-USED			0.00	
1.00	51131827281U	HOOD GRILL E9 L/CHROME-U			0.00	
1.00	51131827282U	HOOD GRILL E9/R CHROME-U			0.00	
11.00	51131827359	MOLDING STRIP E9/PER MET			77.22	
1.00	51135734130U	TAIL PANEL CVR E9-USED			0.00	

OK	Bad	Recommendation	OK	Bad	Recommendation	OK	Bad	Recommendation
E9 COUPE								

You have the right to receive a written estimate or to waive receipt of that estimate if the cost of repairs will exceed \$350.00. We will provide an estimate for your specific problem/repair. Our hourly rate is \$150.00.

I authorize Korman Autoworks, Inc. to diagnose and repair my vehicle without providing a written estimate.

(This repair)X_____ (Permanently)X_____

I authorize repairs that do not exceed \$_____. X_____

I request a written estimate X_____

I wish to receive my old parts X_____ Received (initial) X_____

I do not want my old parts X_____

Labor : \$0.00**Parts : \$47,596.47****Sublet : \$0.00****Other Fees : \$0.00****Supplies/Haz \$0.00****Subtotal : \$47,596.47****Sales Tax : \$3,209.25****Total : \$50,805.72****Estimate Only**

**2629 RANDLEMAN ROAD
GREENSBORO, NC 27406
336-275-1494**

Center : 2

Vehicle : 20
License :
VIN :
Fleet #:
Engine : Trans :
Mileage :

OK	Bad	Recommendation	OK	Bad	Recommendation	OK	Bad	Recommendation
E9 COUPE								

I do not want my old parts X

Estimate Only

KORMAN AUTOWORKS, INC.

**2629 RANDLEMAN ROAD
GREENSBORO, NC 27406
336-275-1494**

Estimate #0013899**Date : 7/17/26****Page : 15****Center : 2**

**Customer : KORMAN AUTOWORKS
Address : 2629 RANDLEMAN ROAD
City : GREENSBORO, NC 27406
Phone 1 : (336) Ext :
Phone 2 : (336) Ext :**

Vehicle : 20**License :****VIN :****Fleet #:****Engine :****Trans :****Mileage :**

Op	Tech	Description	Labor	Parts	Subtotal
Quan	Part Number	Part Description		Price	
0		E9-TRIM	0.00	12627.30	12627.30
4.00	51216650054	DOOR BRAKE PIN-2002/E9/E		20.92	
1.00	51216742131U	DOOR HANDLE E9 D/S-NLA/U		0.00	
1.00	51216754320U	MOLDING E9 DOOR/UPR-D/S-		0.00	
2.00	51216754321U	MOLDING E9 DOOR/UPR-P/S-		0.00	
2.00	51231859731U	HOOD LOCK E3/9/24/2000C-		40.00	
2.00	51245676219	3.0 TRUNK HINGE CVR E9 N		18.42	
1.00	51317740114	W/S GASKET E9		290.46	
1.00	51317740114U	W/S GASKET E9-USED		0.00	
2.00	51317740117U	MOLDING W/S E9 D/S -USED		320.00	
1.00	51317740118	MOLDING W/S E9 P/S		245.92	
2.00	51317740118U	MOLDING W/S E9 P/S-USED		0.00	
3.00	51317740154	REAR WINDOW GSKT E9		854.22	
1.00	51317740167	WINDOW FRAME E9-L/R-NLA		0.00	
1.00	51317740168U	WINDOW FRAME E9-R/R-NLA/		0.00	
2.00	51321812553U	VENT WINDOW ASSY. E9 D/S		0.00	
1.00	51321812554U	VENT WINDOW ASSY. E9 P/S		0.00	
1.00	51326754212U	WINDOW GUIDE BRCKT-E9		15.00	
1.00	51326754224U	MOLDING E9 D/S WINDOW-US		0.00	
2.00	51326754357U	VENT WINDOW KNOB CAP E9/		0.00	
1.00	51338745160U	WINDOW LIFT E9/2000C-ELE		0.00	
1.00	51338745161U	WINDOW LIFT E9/2000C-ELE		0.00	
1.00	51351375398	WINDOW MTR R E3/9/12/23/		0.00	
1.00	51367740107	REAR WINDOW LIFT GSKT-L		75.00	

OK	Bad	Recommendation	OK	Bad	Recommendation	OK	Bad	Recommendation
E9 COUPE								

You have the right to receive a written estimate or to waive receipt of that estimate if the cost of repairs will exceed \$350.00. We will provide an estimate for your specific problem/repair. Our hourly rate is \$150.00.

I authorize Korman Autoworks, Inc. to diagnose and repair my vehicle without providing a written estimate.

(This repair)X _____ (Permanently)X _____

I authorize repairs that do not exceed \$ _____. X _____

I request a written estimate X _____

I wish to receive my old parts X _____ Received (initial) X _____

I do not want my old parts X _____

Labor : \$0.00**Parts : \$47,596.47****Sublet : \$0.00****Other Fees : \$0.00****Supplies/Haz \$0.00****Subtotal : \$47,596.47****Sales Tax : \$3,209.25****Total : \$50,805.72****Estimate Only**

KORMAN AUTOWORKS, INC.

**2629 RANDLEMAN ROAD
GREENSBORO, NC 27406
336-275-1494**

Estimate #0013899**Date : 7/17/26****Page : 16****Center : 2**

Customer : KORMAN AUTOWORKS
Address : 2629 RANDLEMAN ROAD
City : GREENSBORO, NC 27406
Phone 1 : (336) Ext :
Phone 2 : (336) Ext :

Vehicle : 20**License :****VIN :****Fleet #:****Engine :****Trans :****Mileage :**

Op	Tech	Description	Labor	Parts	Subtotal
Quan	Part Number	Part Description	Reason for Replacement	Price	
0		E9-TRIM	0.00	12627.30	12627.30
2.00	51367740108	REAR WINDOW LIFT GSKT-R		150.00	
1.00	51367740125U	MOLDING UPR D/S E9-NLA-U		0.00	
1.00	51367740126U	MOLDING UPR P/S E9-NLA-U		75.00	
1.00	51367740132U	MOLDING C PILLAR E9-USED		0.00	
2.00	51367780179	HEADLINER TRIM CUP E9 IN		17.80	
1.00	51371810310U	WINDOW REGULATOR E9 R/R-		0.00	
1.00	51371811137U	SIDE REAR WINDOW E9 D/S-		0.00	
4.00	51376740140	REAR WINDOW BRCKT E9-NLA		106.16	
4.00	51376740175	WINDOW GSKT E9 SIDE		160.44	
1.00	51471810890	TRUNK TRIM PANEL E9-P/S		98.90	
1.00	51471810889	TRUNK TRIM PANEL E9 D/S		98.79	
1.00	51471811966U	TRUNK BOX E9 12/68-11/75		0.00	
1.00	51476740133U	RAIL D/S E9/2000C-NLA/US		0.00	
1.00	51711813032	3.0CS R/F INNER F/W C/PL		86.22	
1.00	51727770025U	EDGE PROTECTION E9 D/S-U		0.00	
1.00	51727770026U	EDGE PROTECTION E9 P/S-U		0.00	
24.00	51951811281	GREY TRUNK FABRIC /METER		1603.44	
1.00	54121801211	S/ROOF SEAL 02/E3/9/12		31.59	
3.00	54121870086	S/ROOF GSKT-EARLY BIG 6		95.49	
3.00	54129734131	S/ROOF SEAL 02-REAR/E9		241.08	
1.00	54139734132	BOWDEN CABLE 2002/E3/9		23.00	
5.00	51481811883	HOOD INSULATION E9 /SET-		477.85	
4.00	51111838076	MOLDING CLIP V/APPS		4.28	

OK	Bad	Recommendation	OK	Bad	Recommendation	OK	Bad	Recommendation
E9 COUPE								

You have the right to receive a written estimate or to waive receipt of that estimate if the cost of repairs will exceed \$350.00. We will provide an estimate for your specific problem/repair. Our hourly rate is \$150.00.

I authorize Korman Autoworks, Inc. to diagnose and repair my vehicle without providing a written estimate.

(This repair)X_____ (Permanently)X_____

I authorize repairs that do not exceed \$_____. X_____

I request a written estimate X_____

I wish to receive my old parts X_____ Received (initial) X_____

I do not want my old parts X_____

Labor : \$0.00**Parts : \$47,596.47****Sublet : \$0.00****Other Fees : \$0.00****Supplies/Haz \$0.00****Subtotal : \$47,596.47****Sales Tax : \$3,209.25****Total : \$50,805.72****Estimate Only**

KORMAN AUTOWORKS, INC.

**2629 RANDLEMAN ROAD
GREENSBORO, NC 27406
336-275-1494**

Estimate #0013899**Date : 7/17/26****Page : 17****Center : 2**

Customer : KORMAN AUTOWORKS
Address : 2629 RANDLEMAN ROAD
City : GREENSBORO, NC 27406
Phone 1 : (336) Ext :
Phone 2 : (336) Ext :

Vehicle : 20**License :****VIN :****Fleet #:****Engine :****Mileage :****Trans :**

Op	Tech	Description		Labor	Parts	Subtotal
Quan	Part Number	Part Description	Reason for Replacement		Price	
0	E9-TRIM			0.00	12627.30	12627.30
54.00	51135780108	BODYNUT BOLT			204.66	
1.00	51361837225	QTR WINDOW RUBBER E9-D/S			58.71	
5.00	51481811883	HOOD INSULATION E9 /SET-			472.85	
2.00	51481823438	FIREWALL INS. (CABIN) E9			66.24	
2.00	51716754282	DOOR GSKT E9 D/S-UPPER			655.00	
1.00	51716754286	DOOR FRAME A PILLAR-E9 R			70.32	
1.00	51716754295	DOOR SEAL-SMALL-E9			15.60	
3.00	51141803459	EMBLEM GROMMETT			7.77	
2.00	51141831599	FUSE DECAL (12) 2002/200			11.48	
11.00	51141852899	GROMMET FOR BADGES			19.80	
1.00	51142121107	VIN TAG V/APPS.			13.97	
4.00	51216742120	DOOR HANDLE SPACER			18.56	
5.00	51326654262	WINDOW RUBBER PER METER			265.30	
1.00	51175790035	GLOVE BOX BUMPER V/APPS			15.30	
1.00	51211851494	DOOR STRIKER PLATE-V/A			3.11	
2.00	51321819852U	WINDOW HANDLE STOP DISC-			0.00	
4.00	51321870460	DOOR HANDLE SPRING			14.72	
	E9 INTERIOR			0.00	730.97	730.97
2.00	5133E9U	WINDOW MTR E9-USED			50.00	
2.00	51161825797UP	SUNVISOR PIVOT E9 NLA-US			10.00	
2.00	51167766079	SUNVISOR CLIP E9-IVORY N			12.56	
1.00	51167766086U	ASHTRAY E9 REAR ENG. SAD			15.63	
1.00	51211803751	DOOR HANDLE CVR 2002/E3/			22.00	

OK	Bad	Recommendation	OK	Bad	Recommendation	OK	Bad	Recommendation
E9 COUPE								

You have the right to receive a written estimate or to waive receipt of that estimate if the cost of repairs will exceed \$350.00. We will provide an estimate for your specific problem/repair. Our hourly rate is \$150.00.

I authorize Korman Autoworks, Inc. to diagnose and repair my vehicle without providing a written estimate.

(This repair)X_____ (Permanently)X_____

I authorize repairs that do not exceed \$_____. X_____

I request a written estimate X_____

I wish to receive my old parts X_____ Received (initial) X_____

I do not want my old parts X_____

Labor : \$0.00**Parts : \$47,596.47****Sublet : \$0.00****Other Fees : \$0.00****Supplies/Haz \$0.00****Subtotal : \$47,596.47****Sales Tax : \$3,209.25****Total : \$50,805.72****Estimate Only**

KORMAN AUTOWORKS, INC.

**2629 RANDLEMAN ROAD
GREENSBORO, NC 27406
336-275-1494**

Estimate #0013899**Date : 7/17/26****Page : 18****Center : 2**

Customer : KORMAN AUTOWORKS
Address : 2629 RANDLEMAN ROAD
City : GREENSBORO, NC 27406
Phone 1 : (336) **Ext :**
Phone 2 : (336) **Ext :**

Vehicle : 20**License :****VIN :****Fleet #:****Engine :****Mileage :****Trans :**

Op	Tech	Description		Labor	Parts	Subtotal
	Quan	Part Number	Part Description	Reason for Replacement	Price	
0		E9 INTERIOR			730.97	730.97
1.00		51211803751U	DOOR HANDLE CVR 2002/E3/		0.00	
2.00		51211803752U	DOOR HANDLE CVR 2002/E3/		0.00	
1.00		51211812014	DOOR HANDLE E9 & 2000C P		150.00	
1.00		51431811531U	DOOR PANEL E9-L/R-BLK-US		0.00	
1.00		51431832253U	ARMREST E9 L/R MARINE BL		0.00	
1.00		51431832254U	ARMREST E9 R/R MARINE BL		0.00	
1.00		51431833233U	DOOR PANEL E9 L/R NAVY/U		0.00	
1.00		51431833234U	DOOR PANEL E9 R/R NAVY/U		0.00	
2.00		52101803743	SEAT RAIL HANDLE 02/3/9/		26.88	
2.00		52101803743U	SEAT RAIL HANDLE 2002/E2		0.00	
1.00		52101823887	SEAT HANDLE 02/E9		26.41	
3.00		52101828905	HEADREST TRIM BK-2002/E3		54.66	
2.00		52101828905U	HEADREST TRIM BK-2002/E3		0.00	
1.00		31NARDIHUBE9	S/W HUB W/BMW HORN E9		351.00	
7.00		51211819328	DOOR TRIM CLIP-2002/E9		11.83	
		E9 VEHICLE ELECTRICS			2993.09	2993.09
1.00		33525COUPEU	STRUTBAR/BAT MOUNT E9-NL		100.00	
1.00		61211353680	BATTERY HOLD DOWN 02/E3/		35.64	
1.00		61211353680U	BATTERY HOLD DOWN 02/E3/		0.00	
1.00		61311353428	HAZARD SWITCH-EURO 02,E3		148.03	
1.00		61311355322	T/S SWITCH E9		289.74	
2.00		61311355415U	WINDOW SWITCH E9-USED		0.00	
1.00		61311356193	HAZARD SWITCH 2002 >8/73		69.13	

OK	Bad	Recommendation	OK	Bad	Recommendation	OK	Bad	Recommendation
E9 COUPE								

You have the right to receive a written estimate or to waive receipt of that estimate if the cost of repairs will exceed \$350.00. We will provide an estimate for your specific problem/repair. Our hourly rate is \$150.00.

I authorize Korman Autoworks, Inc. to diagnose and repair my vehicle without providing a written estimate.

(This repair)X_____ (Permanently)X_____

I authorize repairs that do not exceed \$_____. X_____

I request a written estimate X_____

I wish to receive my old parts X_____ Received (initial) X_____

I do not want my old parts X_____

Labor : \$0.00**Parts :** \$47,596.47**Sublet :** \$0.00**Other Fees :** \$0.00**Supplies/Haz** \$0.00**Subtotal :** \$47,596.47**Sales Tax :** \$3,209.25**Total :** \$50,805.72**Estimate Only**

KORMAN AUTOWORKS, INC.

**2629 RANDLEMAN ROAD
GREENSBORO, NC 27406
336-275-1494**

Estimate #0013899**Date : 7/17/26****Page : 19****Center : 2**

Customer : KORMAN AUTOWORKS
Address : 2629 RANDLEMAN ROAD
City : GREENSBORO, NC 27406
Phone 1 : (336) **Ext :**
Phone 2 : (336) **Ext :**

Vehicle : 20**License :****VIN :****Fleet #:****Engine :****Trans :****Mileage :**

Op	Tech	Description		Labor	Parts	Subtotal
	Quan	Part Number	Part Description	Reason for Replacement	Price	
0		E9 VEHICLE ELECTRICS			0.00	2993.09
	1.00	61321357380	IGN SWITCH E9 11/73-11/7		225.76	
	1.00	61611354583U	WIPER MTR E3/E9-USED		150.00	
	2.00	61611365975	WIPER ARM 02/E9/2000C BL		192.22	
	2.00	61611365975U	WIPER ARM 02/E9/2000C BL		0.00	
	1.00	61618744138U	WIPER ARM E9 >4/71 D/S S		0.00	
	1.00	61618744140U	WIPER ARM E9 >4/71 P/S S		0.00	
	2.00	61661355299	H/L WASHER VALVE 02/E3/9		31.52	
	1.00	61671359116	W/S WASHER PUMP-02/E3/9/		142.62	
	1.00	63121354448	H/LIGHT ADJ SCREW E9 3.0		0.00	
	15.00	63121811910	H/L CVR NUT E9		98.85	
	2.00	63121811922U	H/L CVR PLATE E9-P/S		0.00	
	1.00	63131811099	T/S LENS E9 L/F EURO		98.86	
	1.00	63131811099U	T/S LENS E9 L/F-US SPEC		0.00	
	1.00	63131811100U	T/S LENS E9 R/F-US SPEC		0.00	
	1.00	63131811101U	T/S BULB SOCKET E9 D/S U		0.00	
	2.00	63131811102U	T/S BULB SOCKET E9 P/S-U		0.00	
	1.00	63131811105U	T/S BOW E9 D/S-USED		0.00	
	1.00	63131811106U	T/S BOW E9 P/S-USED		0.00	
	1.00	63141353995U	SIDE MARKER LIGHT E9 L/R		0.00	
	1.00	63141352996U	SIDE MARKER LIGHT E9 R/R		0.00	
	1.00	63211353155U	T/LIGHT BULB SOCKET E9 D		0.00	
	1.00	63211353159U	T/LIGHT LENS 2000C/CS-D/		0.00	
	1.00	61121350305	BATTERY CABLE-NEG 2000/S		53.90	

OK	Bad	Recommendation	OK	Bad	Recommendation	OK	Bad	Recommendation
E9 COUPE								

You have the right to receive a written estimate or to waive receipt of that estimate if the cost of repairs will exceed \$350.00. We will provide an estimate for your specific problem/repair. Our hourly rate is \$150.00.

I authorize Korman Autoworks, Inc. to diagnose and repair my vehicle without providing a written estimate.

(This repair)X_____ (Permanently)X_____

I authorize repairs that do not exceed \$_____. X_____

I request a written estimate X_____

I wish to receive my old parts X_____ Received (initial) X_____

I do not want my old parts X_____

Labor : \$0.00**Parts : \$47,596.47****Sublet : \$0.00****Other Fees : \$0.00****Supplies/Haz \$0.00****Subtotal : \$47,596.47****Sales Tax : \$3,209.25****Total : \$50,805.72****Estimate Only**

KORMAN AUTOWORKS, INC.

**2629 RANDLEMAN ROAD
GREENSBORO, NC 27406
336-275-1494**

Estimate #0013899**Date : 7/17/26****Page : 20****Center : 2**

Customer : KORMAN AUTOWORKS
Address : 2629 RANDLEMAN ROAD
City : GREENSBORO, NC 27406
Phone 1 : (336) Ext :
Phone 2 : (336) Ext :

Vehicle : 20**License :****VIN :****Fleet #:****Engine :****Trans :****Mileage :**

Op	Tech	Description		Labor	Parts	Subtotal
	Quan	Part Number	Part Description	Reason for Replacement	Price	
0		E9 VEHICLE ELECTRICS		0.00	2993.09	2993.09
1.00		61121351563U	WIRING HARNESS E9/GAUGES		0.00	
6.00		61131355345	CABLE CLAMP 2002/3.0CS-N		7.44	
1.00		61138460132	FUSE BOX CVR 2002 (6 FUS		25.50	
1.00		61211353680	BATTERY HOLD DOWN 02/E3/		34.64	
1.00		61311352949	HEADLIGHT DIMMER SWITCH-		433.00	
1.00		61311355358	HAZARD SWITCH 2002 8/73>		82.04	
1.00		61311355358U	HAZARD SWITCH 2002 8/73>		0.00	
1.00		61311355791	H/L SWITCH 2002		97.36	
1.00		61311356193	HAZARD SWITCH 2002 >8/73		69.13	
1.00		61311357913	RELAY WIPER/WASHER 02/E3		190.00	
1.00		61311363638	T/S SWITCH E9 S/N 43XX>		185.62	
1.00		61311364272	TEMP SWITCH 91C		17.88	
1.00		61318360420	BK LIGHT SWITCH-2 POLE-L		44.04	
1.00		61311362792	DOOR SWITCH EARLY S/POLE		30.61	
1.00		61661350871	W/S WASHER BOTTLE-2002/E		105.90	
3.00		61661350871U	W/S WASHER BOTTLE 02/E3/		0.00	
2.00		61661364807	W/S WASHER CAP-2002/E9/2		33.66	
		E9 GAUGES 3.0		0.00		
1.00		62111354848U	GAUGE SUPPORT E9-USED		0.00	
1.00		62111356399U	SPEEDO GAUGE E9 KPH/USED		0.00	
1.00		62121810618U	SPEEDO GAUGE E9 MPH/USED		0.00	
2.00		62131357111U	CLOCK E9/USED		0.00	
1.00		62131359271U	TACHOMETER E9 6 CYL/USED		0.00	

OK	Bad	Recommendation	OK	Bad	Recommendation	OK	Bad	Recommendation
E9 COUPE								

You have the right to receive a written estimate or to waive receipt of that estimate if the cost of repairs will exceed \$350.00. We will provide an estimate for your specific problem/repair. Our hourly rate is \$150.00.

I authorize Korman Autoworks, Inc. to diagnose and repair my vehicle without providing a written estimate.

(This repair)X _____ (Permanently)X _____

I authorize repairs that do not exceed \$ _____. X _____

I request a written estimate X _____

I wish to receive my old parts X _____ Received (initial) X _____

I do not want my old parts X _____

Labor : \$0.00**Parts : \$47,596.47****Sublet : \$0.00****Other Fees : \$0.00****Supplies/Haz \$0.00****Subtotal : \$47,596.47****Sales Tax : \$3,209.25****Total : \$50,805.72****Estimate Only**

KORMAN AUTOWORKS, INC.

**2629 RANDLEMAN ROAD
GREENSBORO, NC 27406
336-275-1494**

Estimate #0013899**Date : 7/17/26****Page : 21****Center : 2**

**Customer : KORMAN AUTOWORKS
Address : 2629 RANDLEMAN ROAD
City : GREENSBORO, NC 27406
Phone 1 : (336) Ext :
Phone 2 : (336) Ext :**

Vehicle : 20**License :****VIN :****Fleet #:****Engine :****Mileage :****Trans :**

Op	Tech	Description		Labor	Parts	Subtotal
	Quan	Part Number	Part Description		Price	
0		E9 GAUGES 3.0		0.00		
	2.00	62111812235U	INSTRUMENT GAUGE E9 GAS/		0.00	
		E9 LIGHTING		0.00	223.95	223.95
	1.00	63318690100	DOME LIGHT 02 W/SROOF /E		199.00	
	1.00	63318690150	DOME LIGHT LENS 02 W/SR,		24.95	
		E9 HVAC		0.00	443.59	443.59
	1.00	64111351375	HEATER CLAMP E3/E9		3.00	
	1.00	64111355648U	HTR BOX W/CONTROLS E9/US		0.00	
	1.00	64111357890	BLOWER MOTOR E9/E3		350.41	
	2.00	64111357890U	BLOWER MOTOR E3/9/2000C-		0.00	
	9.00	64114674162	HEATER BOX CLAMP 02/E9/1		17.73	
	3.00	64214674121	COWL DRAIN E9		51.36	
	1.00	64221351340U	DEFROSTER NOZZLE E9/RIGH		0.00	
	1.00	64221810653U	HTR DUCT E9/2000C CTR/US		0.00	
	1.00	35846U	A/C SWITCH E9/2002-USED		0.00	
	3.00	12311268434	A/C MT SPACER BUSHING		21.09	
	1.00	64221351339U	DEFROSTER NOZZLE E9/LEFT		0.00	
		E9 RADIO		0.00	332.00	332.00
	2.00	82260000000	KICK PANELS 4 SPEAKERS 3		302.00	
	1.00	65131111111	CENTER SPEAKER E9		30.00	
		E9 TOOLS		0.00	1002.56	1002.56
	1.00	71111102916	TOOL BOX E3/E9 >1973		499.41	
	1.00	71111113754	TOOL BOX FOAM E3/9/12/21		43.00	

OK	Bad	Recommendation	OK	Bad	Recommendation	OK	Bad	Recommendation
E9 COUPE								

You have the right to receive a written estimate or to waive receipt of that estimate if the cost of repairs will exceed \$350.00. We will provide an estimate for your specific problem/repair. Our hourly rate is \$150.00.

I authorize Korman Autoworks, Inc. to diagnose and repair my vehicle without providing a written estimate.

(This repair)X _____ (Permanently)X _____

I authorize repairs that do not exceed \$ _____. X _____

I request a written estimate X _____

I wish to receive my old parts X _____ Received (initial) X _____

I do not want my old parts X _____

Labor : \$0.00**Parts : \$47,596.47****Sublet : \$0.00****Other Fees : \$0.00****Supplies/Haz \$0.00****Subtotal : \$47,596.47****Sales Tax : \$3,209.25****Total : \$50,805.72****Estimate Only**

KORMAN AUTOWORKS, INC.

**2629 RANDLEMAN ROAD
GREENSBORO, NC 27406
336-275-1494**

Estimate #0013899**Date : 7/17/26****Page : 22****Center : 2**

Customer : KORMAN AUTOWORKS
Address : 2629 RANDLEMAN ROAD
City : GREENSBORO, NC 27406
Phone 1 : (336) Ext :
Phone 2 : (336) Ext :

Vehicle : 20**License :****VIN :****Fleet #:****Engine :****Mileage :****Trans :**

Op	Tech	Description		Labor	Parts	Subtotal
	Quan	Part Number	Part Description	Reason for Replacement	Price	
0		E9 TOOLS			0.00 1002.56	1002.56
	5.00	71111117105	TOOL BOX E3/12/21/24/E9		436.95	
	1.00	71121103150U	JACK HANDLE E3/9/12-USED		0.00	
	1.00	71121113380U	JACK E9 / USED		0.00	
	3.00	72111840331U	SEATBELT E9 FRT/FM/USED		0.00	
	1.00	71111179522U	H2O PUMP PLIERS-USED		0.00	
	1.00	71119690009	WRENCH M17X19-OPEN END		23.20	

OK Bad Recommendation OK Bad Recommendation OK Bad Recommendation

E9 COUPE

You have the right to receive a written estimate or to waive receipt of that estimate if the cost of repairs will exceed \$350.00. We will provide an estimate for your specific problem/repair. Our hourly rate is \$150.00.

I authorize Korman Autoworks, Inc. to diagnose and repair my vehicle without providing a written estimate.

(This repair)X_____ (Permanently)X_____

I authorize repairs that do not exceed \$_____. X_____

I request a written estimate X_____

I wish to receive my old parts X_____ Received (initial) X_____

I do not want my old parts X_____

Labor : \$0.00**Parts : \$47,596.47****Sublet : \$0.00****Other Fees : \$0.00****Supplies/Haz \$0.00****Subtotal : \$47,596.47****Sales Tax : \$3,209.25****Total : \$50,805.72****Estimate Only**